

Диагностирует следующие штатные отопители Вебасто

BMW (E60 / E61 / E66 / E66 / X5(E53) аналоговый)

- Citroen (Evasion / C8 / Jumpy)
 - Chevrolet (Cruze / Malibu / Orlando / Trax / Voyager)
 - Dodge (Caravan)
 - Ford (Galaxy I / Galaxy II / Transit)
 - Land Rover (Freelander 2 / Discovery 3 / Discovery 4)
 - Range Rover Sport
 - Mercedes (W202 / W210 / W211 / W220 / Sprinter / Vito)
 - Opel (Astra J / Cascada / Insignia / Meriva B / Mokka / Omega / Vivaro / Zafira)
 - Peugeot (806 / 807 / Boxer / Espace)
 - Seat (Alhambra I / Alhambra II (7N) / Altea / Leon)
 - Skoda (Octavia / Superb / Yeti)
 - Volkswagen (Amarok / Caddy / Crafter / Golf (5, Plus) / Passat (B6,CC) / Sharan I / Touareg / Touran / Transporter T4, T5, T5GP Multivan, Caravella)
 - Volvo (S60 II и V60 и XC60 II 2011-2012 + обновить ПО 31257530: Software Fernbedienung и 30756215: Software Timer)
 - Volvo (S80 II и V70 III и XC70 III 2008-2012 + обновить ПО 30790221: Software-Fernbedienung и 30776785: Software-Timer)
 - Webasto Air Top Evo 3900 / Air Top Evo 5500
 - Webasto Thermo Top C, Z, V, E, P, T (aftermarket)
-
- AUDI A4 B8 2007-2015 (Eberspacher B5S F / D5S F)
 - AUDI A4 Allroad B8 2009-2015 (Eberspacher B5S F / D5S F)
 - AUDI A4 B9 2015 > (Eberspacher B5S F / D5S F)
 - AUDI A4 Allroad B9 2016 > (Eberspacher B5S F / D5S F)
 - AUDI A5 8T 2007-2016 (Eberspacher B5S F / D5S F)
 - AUDI A5 2016 > (Eberspacher B5S F / D5S F)
 - AUDI A6 C7 2011 > (Eberspacher B5S F / D5S F)
 - AUDI A6 Allroad C7 2012 > (Eberspacher B5S F / D5S F)
 - AUDI A7 4G 2010 > (Eberspacher B5S F / D5S F)

- **AUDI A8 D4 2010 > (Eberspacher B5S F / D5S F)**
- **AUDI Q5 2008 > (Eberspacher B5S F / D5S F)**

Диагностирует следующие штатные отопители Eberspacher Eberspacher

- **AUDI Q7 II 2015 > (Eberspacher B5S F / D5S F)**
- **Ford Transit 2000-2006 (Hydronic)>**
- **Ford Transit 206 > (Hydronic)**
- **Ford Transit 2014 > (Hydronic)**
- **Land Rover Discovery Sport 2014 > (Hydronic II)**
- **Land Rover Range Rover Sport 2013 > (Hydronic II)**
- **Land Rover Range Rover Vogue 2012 > (Hydronic II)**
- **Porsche Cayenne II 2010-2015 (Eberspacher B5S F / D5S F)**
- **Porsche Cayenne III 2016 > (Eberspacher B5S F / D5S F)**
- **Seat Alahambra I 2000-2010 (Eberspacher B5S F / D5S F)**
- **VW Sharan I 2003-2010 (Hydronic II)**
- **VW Touareg NF 2010 > (Eberspacher B5S F / D5S F)**
- **Eberspacher Aftermarket**

<https://webastomsk.ru/>